CDIATION UTAH DIY. OF ENVIRON ENTAL RESPONSE AND RE INCIDENT

T OF NATURAL RESOURCES Received B OIL. GAS AND MINING

1594 West North Temple, Suite 1210

REPOR THEIN

GOBP 1A68RTY

Kathleen Clarke Executa meetor

Salt Lake City, Utah 84114-5801 Firm Kandolin

Company Prector

Kennecotto Utah Copper

Phone:

801-569-6208

Date:

3/28/2001 **Time:**

19:00

Incident Began:

3/28/2001 **Time:**

9:30

Incident Ended:

3/28/2001 Time:

10:30

RESPONSIBLE PARTY

Name:

Kennecott Utah Copper

Address:

Phone:

801-569-6208

INCIDENT SUMMARY

While cleaning slime from the 48" tailings line a blockage occurred. The concentrator was operating at about 75% but about 111 tons of tailings overflowed from the line. The tailings contained about 14 lbs of Cr, 4lbs of As, and 1 lb of Pb. Entire spill was contained on roadway and between pipelines. Champion has been hired to use vac trucks and/or excavation to retain all spilled material to mill pile where it will be reprocessed.

Incident Location: 1/2 mile north of Barney's Canyon Road on 48" tail

Nearest City:

Copperton

Highway:

Milemarker:

0

NRC Report #: 561032

County:

Salt Lake

In Waterway:

LEAD AGENCY:

S&HW

Contact:

Notify by e-mail

ASSISTANCE PROVIDED:

NOTIFICATIONS MADE FOR THIS INCIDENT:

Agency

Contact

Date

Time

Incident notification reports are prepared by DERR using information provided by the reporting party. The information is considered preliminary and is subject to revision. The reported incident and associated details may or may not be valid. Additional information concerning this incident may be available by contacting the Division at (801) 536-4102

M/035/011